## **SAFEX**

## **INTERNATIONAL**

(Since 1954)

## **INCIDENT NOTICE**

(Kindly direct all correspondence to the Secretary General)

**INCIDENT TITLE: Chemical Reaction in Ammonium Nitrate waste bin** 

DATE POSTED 7 April 2012	REFERENCE IN 21-10	<b>SOURCE</b> Anonymous
	INCIDENT OUTLINE	
When did it happen?	26 <sup>th</sup> November 2020	
Who experienced it?	Mining Services Operation - Africa	
Where did it happen?	Moatize, Mozambique	
What material was involved?	Ammonium Nitrate prill	
What happened?	fumes issuing from a waste bin use	duties, an operator noticed white ed for ammonium nitrate prill spills. pproached the bin, and emptied it ceased.
Why did it happen – theory?	The bin contents were contaminated with carbonaceous materials from the mine. The mine rock has also been shown to be reactive in some cases.	
What was the impact?	The contaminated material was di	sposed of on-bench.

|--|

No **Enclosure** 

No **Subsequent report** 

**COMMENT** 

Highlights the potential for contamination, and the need for training and rehearsal of emergency procedures. Value of incident

**Comment** 

**DISTRIBUTED BY:** Piet Halliday

Secretary General, SAFEX International ( <a href="www.safex-international.org">www.safex-international.org</a>)
Tel: +27 82 5565351; Tel / Fax: +27 11 7041743
e-mail: <a href="mailto:secretariat@safex-international.org">secretariat@safex-international.org</a>